



NYSDEC SPILL REPORT FORM



DEC REGION: 7 SPILL NUMBER: 0601915
SPILL NAME: NIMO SUBSTATION DEC LEAD: HDWARNER
SPILL DATE: 05/22/2006 SPILL TIME: 11:30 am
CALL RECEIVED DATE: 05/22/2006 RECEIVED TIME: 12:54 pm

SPILL LOCATION

PLACE: NIMO SUBSTATION COUNTY: Onondaga
STREET: 800 FACTORY AVE TOWN/CITY: Salina
COMMUNITY: SALINA
CONTACT: SUE SWANSON CONTACT PHONE: (315) 460-2334

CONT. FACTOR: Equipment Failure SPILL REPORTED BY: Responsible Party
FACILITY TYPE: Institutional, Educational, Gov., Other WATERBODY:

CALLER REMARKS:

NON PCB- TRANSFORMER LEAKING, CONTAINED ON CONCRETE: CLEAN UP WILL BE DONE ON 5/31

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
transformer oil	Petroleum	3 G	0 G	Soil,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NIMO SUBSTATION	800 FACTORY AVE SALINA NY	SUE SWANSON
		(315) 460-2334

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure
----------	-----------	----------	-------	--------	-------------	-----------	---------------

DEC REMARKS:

PIN

T & A

COST CENTER

CLASS: D4 CLOSE DATE: 09/05/2006 MEETS STANDARDS: False



NYSDEC SPILL REPORT FORM



DEC REGION: 7 SPILL NUMBER: 1403464
SPILL NAME: NAT GRID TEALL AVE STATION 72 DEC LEAD: RJBRAZEL
SPILL DATE: 07/01/2014 SPILL TIME: 11:22 am
CALL RECEIVED DATE: 07/01/2014 RECEIVED TIME: 11:22 am

SPILL LOCATION

PLACE: NAT GRID TEALL AVE STATION 72 COUNTY: Onondaga
STREET: 800 FACTORY AVE TOWN/CITY: Salina
COMMUNITY: SALINA
CONTACT: RICHARD FOX CONTACT PHONE: (315) 460-2385

CONT. FACTOR: Equipment Failure SPILL REPORTED BY: Other
FACILITY TYPE: Commercial/Industrial WATERBODY:

CALLER REMARKS:

weeping from transformers onto stone, found during field site inspection, c/u unknown, 9 transformers leaking- all less than 50 parts/ per million pcb

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
dielectric fluid	Petroleum	100 G		Soil,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NAT GRID	800 FACTORY AVE SALINA NY	RICHARD FOX
		(315) 460-2385

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure
----------	-----------	----------	-------	--------	-------------	-----------	---------------

DEC REMARKS:

cleaning pending removal of transformers as part of substation upgrade

7/9/14 Spoke to Rich Fox. Active substation. NG looking to do a rebuild and asked Rich Fox for estimate on cleanup. Four previous spills that were closed, so Rich opened up new spill. There are 12 transformers in the bank, nine old-style and 3 mc recently installed, at station and records indicate less than 50ppm PCBs per NG's former laboratory. Gravel sub-base over soil. Rich is going to check into getting oil samples from the transformers as it will be approximately a year before the upgrade project will commence.

will reopen spill when upgrade work begins

09/19/14 Received analytical results from 12 transformer oil samples collected by NG. PCBs up to 19 ppm were detected. Sp was re-opened. DEC site visit pending.

10/30/14 Met with R. Fox at substation. Oil residual apparent outer casing and on ground below all 12 transformers. Instructed Rich to clean up all accessible oil residual and place pads/booms below all transformers. Photos in decdocs. Will revisit when substation upgrade project is in planning stages.

Created On: 07/01/2014

Date Printed: 11/29/2018

Last Updated: 01/07/2016

FOIL063045



NYSDEC SPILL REPORT FORM



DEC REGION: 7 SPILL NUMBER: 1403464
SPILL NAME: NAT GRID TEALL AVE STATION 72 DEC LEAD: RJBRAZEL

PIN

T & A

COST CENTER

CLASS: C3

CLOSE DATE:

MEETS STANDARDS: False



NYSDEC SPILL REPORT FORM



DEC REGION: 7 SPILL NUMBER: 1503529
SPILL NAME: NATIONAL GRID AT TEALL AVE SUBSTATION DEC LEAD: CXROSSI
SPILL DATE: 07/01/2015 SPILL TIME: 10:00 am
CALL RECEIVED DATE: 07/01/2015 RECEIVED TIME: 10:10 am

SPILL LOCATION

PLACE: NATIONAL GRID AT TEALL AVE SUBSTATION COUNTY: Onondaga
STREET: 800 FACTORY AVE TOWN/CITY: Salina
COMMUNITY: SALINA
CONTACT: JASON BRESSETT CONTACT PHONE: (315) 741-0997

CONT. FACTOR: Equipment Failure SPILL REPORTED BY: Other
FACILITY TYPE: Commercial Vehicle WATERBODY:

CALLER REMARKS:
cleanup pending

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
hydraulic oil	Petroleum	20	20	Soil,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NATIONAL GRID	NY	

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure
----------	-----------	----------	-------	--------	-------------	-----------	---------------

DEC REMARKS:

op Tech remediated. Report received 7/15/15

PIN

T & A

COST CENTER

CLASS: D4 CLOSE DATE: 07/08/2015 MEETS STANDARDS: True



NYSDEC SPILL REPORT FORM



DEC REGION: 7 SPILL NUMBER: 1802404
SPILL NAME: TEAL AVE SUBSTATION DEC LEAD: SMFITZGE
SPILL DATE: 05/31/2018 SPILL TIME: 10:15 am
CALL RECEIVED DATE: 05/31/2018 RECEIVED TIME: 11:10 am

SPILL LOCATION

PLACE: TEAL AVE SUBSTATION COUNTY: Onondaga
STREET: 800 FACTORY AVE TOWN/CITY: Salina
COMMUNITY: SALINA
CONTACT: ADAM DUERR CONTACT PHONE: (315) 882-1310

CONT. FACTOR: Equipment Failure SPILL REPORTED BY: Other
FACILITY TYPE: Commercial/Industrial WATERBODY:

CALLER REMARKS:
on stone in substation - cleanup in progress

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
transformer oil	Petroleum	10 G		

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NAT GRID	NY	

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure
----------	-----------	----------	-------	--------	-------------	-----------	---------------

DEC REMARKS:

NRC hired for cleanup. Transformer labeled non-PCB. NRC removed contaminated gravel for disposal.
6/19/2018 - Final report received.

<u>PIN</u>	<u>T & A</u>	<u>COST CENTER</u>
------------	------------------	--------------------

CLASS: D4 CLOSE DATE: 06/19/2018 MEETS STANDARDS: False



NYSDEC SPILL REPORT FORM



DEC REGION: 7 SPILL NUMBER: 9503252
SPILL NAME: NIMO SUBSTATION DEC LEAD: CFMANNES
SPILL DATE: 06/15/1995 SPILL TIME: 11:50 am
CALL RECEIVED DATE: 06/15/1995 RECEIVED TIME: 1:36 pm

SPILL LOCATION

PLACE: NIMO SUBSTATION COUNTY: Onondaga
STREET: TEAL AVE. FACTORY AVE. TOWN/CITY: Salina
COMMUNITY: SALINA
CONTACT: _____ CONTACT PHONE: _____

CONT. FACTOR: Equipment Failure SPILL REPORTED BY: Responsible Party
FACILITY TYPE: Commercial/Industrial WATERBODY: _____

CALLER REMARKS:
MALFUNCTION ON PUMPING EQUIPMENT. CREW ON SCENE CLEANING.

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
non PCB oil	Petroleum	100 G	0 G	Soil,
transformer oil	Petroleum	0 L	0 L	Soil,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
NIMO	FACTORY AVENUE SYRACUSE NY	(315) 460-2421

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure
----------	-----------	----------	-------	--------	-------------	-----------	---------------

DEC REMARKS:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was "CM"

PIN

T & A

COST CENTER

CLASS: C3 CLOSE DATE: 10/31/1995 MEETS STANDARDS: False